

... SPECIAL OFFER...

Good pictures make GREAT ENLARGEMENTS

Order Now-

GET A FREE COLOR ENLARGEMENT

**PAY
FOR 3**



**GET ONE
FREE**



8x10's or 5x7's

12 OZ. PHOTO MUG

Kids (and adults, too) will love this 12-oz. stain-resistant polystyrene photo mug. Photo area is 1 3/4-in. diameter. Made from your color or black and white photo.



ONLY **2.89**

ORDER FORM

ENCLOSE ORDER FORM WITH ORDER

QTY.	ITEM	NEG #	PRICE EA.
	WALLET PHOTOS		12 FOR 3.89 EA.
	IS IT		2.89 EA.
	GEMENTS		3
		195656	3

Color Wallet P

Made from one 35mm negative. Add \$1.00 made from photo or other negative size.

12 FOR ONLY \$3.89

SITE: TIDEWATER BALING

NEWARK, NJ

DATE: AUGUST 16, 1989

PHOTO BY: D. DELAP

IMPORTANT: DO NOT CUT NEGATIVES

ALLOW 2-3 WEEKS FOR DELIVERY

4		14		23A		33	
4A		14A		24		33A	
5		15		24A		34	
5A		15A		25		34A	
6		16		25A		35	
6A		16A		26		35A	
7		17		26A		36	
7A		17A		27		36A	
8		18		27A			
8A		18A		28			
9							


CRYSTALLITE FRAME

Have your favorite negative turned into a beautifully framed enlargement. This clear lucite easel backed frame stands or hangs vertically or horizontally.

INCLUDES ENLARGEMENT

5x7 ONLY **4.89 EA.**

8x10 ONLY **6.99 EA.**





SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

AUG 1989

Railroad track bordering
northern side of
"hot" zone.



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

A Point at which
proposed fence will
be erected.

AUG 1989



'89 8 16

SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Trees cut down at
eastern side of
"hot" zone.

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

AUG 1989

Water collected in
"hot" zone.

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Water collected at
edge of eastern
border of "hot" zone.

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

AUG 1989

Brush clearing in
"hot" zone

(along east border).



'89 8 16

SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Southwest corner of
Site (between "safe"
zone + "hot" zone).

AUG 1989



89 8 16

SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

AUG 1989

Land fill approved
for use in site
clean up.



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Surveying perimeter
of "hot" zone.

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Levelled brush / trees
on southern border of
"hot" zone.

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

AUG 1989

Trees at eastern
border of "hot" zone
being removed.



SITE: TIDEWATER BALING
NEWARK, NJ

DATE: AUGUST 16, 1989

PHOTO BY: D. DELAP

AUG 1989

Settling of water on
site after rain.

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Foreman overseeing
work from
"Clean" zone.

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Backhoe levelling
brush + small trees.

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

AUG 1989

Backhoe levelling
brush + small trees.

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Beginning to clear
brush + small
trees on south west
Corner of "hot" zone.

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Brush near fence
post (eastern border
of "hot" zone)

AUG 1989

-Cut down by S&D Engineers.



'89 8 16

SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Site initially.

Beginning of Brush
clearing with Backhoe.

AUG 1989



'89 8 16

SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Site before brush
clearing and cutting
down of small trees.

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Small tree cut down by
eastern border of "hot"

Zone. (tree grew through fence—
(Chopped down to replace fence.)

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Brush cleared
by eastern border
of "hot" zone.

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

West side of "hot"
Zone (Rained day before).

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Oily "contaminated"
water (after rain)
in "hot" zone near
Railroad tracks.

AUG 1989



8 16 '89

SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

AUG 1989

Distance view
of Backhoe at
work (from stands)



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

AUG 1989

Backhoe at work.

(Levelling off
uneven ground)



8 16 '89

SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Backhoe at work.

(Building up Berm to
contain / divert
runoff)

AUG 1989



8 16 '89

SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Preparation for
Decontaminating
Backhoe.

AUG 1989



8 16 '89

SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Decontaminating
Back hoe.

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

AUG 1989

"Clean" Fill Used to
Level off site.



8-16-89

SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Site after done
work for day.
(Southern
Border)

AUG 1989



8 16 '89

SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Site after work
done for day.

(Southern
Border)

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

AUG 1989

Site after work
done for day.
(southern
border)



8 16 '89

SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Site after work
done for day.
(southern
border).

AUG 1989



8 16 '89

SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Site after work
done for day.
(southern
border).

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

AUG 1989

Due to large amounts
of rain - undergrowth
much higher in contaminated
zone than previously.



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Pit after being
filled.

AUG 1989

02
03



8 16 '89

SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

Packing up at
end of day.

AUG 1989



SITE: TIDEWATER BALING
NEWARK, NJ
DATE: AUGUST 16, 1989
PHOTO BY: D. DELAP

AUG 1989

Initial flooding point
behind railroad at
back of contaminated zone.